
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S03AA_016MH	Test ID: <u>D1032-013001</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03AA_016MH
0			Water Level	
10.69999981			Dye Test Visible	DYE SEEN AT JOINT
13.5			Dye Test Visible	DYE SEEN AT JOINT
17.10000038			Dye Test Visible	DYE SEEN AT JOINT
20.39999962			Dye Test Visible	DYE SEEN AT JOINT
31			Abandoned Survey	DYE TEST IS COMPLETE